

Prosthetic Parts			IH (Ncm)	CHC (Ncm)	CS (Ncm)
Cement Retained	Healing Abutment		10	10	10
	Abutments		30	20	30
	Temporary Abutments	Titanium	30	NA	30
		Peek	15	NA	NA
	Transfers		10	10	10
Casting	Implant Level Casting		30	20	30
	Multi unit level Casting		Close manually		
Screw Retained	Healing Abutment		10	10	10
	Angled Abutment		30	20	30
	Straight Abutment		30	20	30
	Temporary Abutments		25	15	25
	Transfers		Close manually		
Overdenture	Alpha Loc		30	20	30
	Ball Attachments		30	20	NA
CADCAM	Scanbody		10	10	10
	Tibase		30	20	30
	Premilled Blanks		30	20	30

<b>Implants</b>			Do not exceed the 50 Ncm		
-----------------	--	--	--------------------------	--	--